

PROJECT: MD 509, Governor Run Road

**<u>DESCRIPTION:</u>** Replaced Bridge 4020 over Governor Run. Shoulders will accommodate bicycles and pedestrians.

<u>JUSTIFICATION</u>: This concrete bridge built in 1931 experienced progressive deterioration of the entire structure and hydraulic problems. The bridge opening was not large enough to adequately accommodate existing water flows.

## **SMART GROWTH STATUS:**

Project Not Location Specific or Location Not Determined
Project Within PFA
Grandfathered
Project Outside PFA; Subject to Exception
X Exception Approved by BPW/MDOT

**ASSOCIATED IMPROVEMENTS:** 

Federal Funding By Year of Obligation												
	FFY	FFY	FFY	FFY	FFY	FEDERAL CATEGORY						
PHASE	2003	2004	2005	2006	2007 - 2008							
PP	0	0	0	0	0							
PE	0	0	0	0	0							
RW	0	0	0	0	0							
со	0	0	0	0	0							

**STATUS:** Open to service.

SIGNIFICANT CHANGE FROM FY 2002 - 07 CTP: None.

POTENTIA	AL FUNDING S	SOURCE:		X SPE	X SPECIAL X FEDERAL GENERAL OTHER						
TOTAL			PROJECT CASH FLOW								
PHASE	<b>ESTIMATED</b>	<b>EXPEND</b>	CURRENT	BUDGET					SIX	BALANCE	
	COST	THRU	YEAR	YEAR	FOR P	LANNING P	URPOSES (	ONLY	YEAR	TO	
	(\$000)	2002	2003	2004	2005	2006	2007	2008	TOTAL	COMPLETE	
Planning	0	0	0	(	0	0	0	0	(	0 0	
Engineering	140	140	0	(	0	0	0	0	(	0 0	
Right-of-way	, 2	2	0	(	0	0	0	0	(	0 0	
Construction	n 443	354	89	(	0	0	0	0	89	9 0	
Total	585	496	89	(	0	0	0	0	89	9 0	
Federal-Aid	458	387	71	(	0	0	0	0	7	1 0	

**FUNCTION:** 

STATE - Local

FEDERAL - Local

**STATE SYSTEM**: Secondary

**DAILY TRAFFIC: (USAGE IMPACTS)** 

**CURRENT (2001) - 550** 

PROJECTED (2025) - 800

OPERATING COST IMPACT N/A